

Change Issue 3 to 4; Window & mounting holes moved 7.5mm to right & up 1mm

Change Issue 4 to 5; Height reduced to 888, mounting holes repositioned, LED holes moved 1mm,

Issue 6 changes; countersinking on eight mounting holes deleted & hole size increased to 5mm

Index, Tall Cabinet Front Serv(F100,F120)
PI457, Issue 6, 17-03-03
Pertronic Industries Ltd